

Missouri DNR, Tanks Section Summary Information FFY 2020

General Information Public Record Posted Date 12/1/2020

Total Number of Active UST Sites: 3,286
Total Number of Active USTs: 8,532

Summary Information For On-Site Inspections

Inspection Timeframe: 10/1/19 to 9/30/20
Number of UST Facilities Inspected: 1,545
Percent Compliance (Combined Measure): 76.10%

Summary Information for Releases

Remediation Case Dates Added Timeframe: 10/1/19 to 9/30/20

Number of Remediation Cases Opened: 61

		Cause														
Source			Overfill		Spill		Phys/Mech Damage		Corrosion		Install Problem		Other		Unknown	
	Totals		#	%	#	%	#	%	#	%	#	%	#	%	#	%
	#	%	0	0.00%	0	0.00%	6	9.84%	1	1.64%	0	0.00%	1	1.64%	53	86.89%
Tank	0	0.00%														
Piping	4	6.56%					2	3.28%	1	1.64%			1	1.64%		
Dispenser	2	3.28%					2	3.28%								
STP	2	3.28%					2	3.28%								
Delivery Problem	0	0.00%														
Other	0	0.00%														
Unknown	53	86.89%													53	86.89%

^{*}Release, source, and cause information is based on releases from leaking underground storage tank sites. Source and cause data were collected from release reports submitted to the department.

^{*}Tank, facility, and on-site inspection data is based on active underground storage tanks inspected during Federal Fiscal Year 2020. The on-site inspections Percent Compliance measure is based on the combined performance measure of the significant operational compliance (SOC) requirements.

^{*}Site-specific information can be reviewed by downloading and searching the Missouri Department of Natural Resources

Underground Storage Tanks Database (online version) at:

https://dnr.mo.gov/env/hwp/tanks/epasourceandcause.htm

If you are unable to download and/or print this document and would like a copy, please contact Raechell Henley at Raechell.Henley@dnr.mo.gov or (573) 526-9546.